


Instaliranje USB GPS RX i softvera za sinkronizaciju vremena


1. Zaustavljen Meinberg NTP


Pokušaj iz Start – All Programs - Meinberg – Network Time Protocol – Service Control – Stop NTP Service nije uspio.

Servis je zaustavljen iz Windows Task Manager-a iz Services – NTP




2. Pokrenuta instalacija – USB GPS U-blox7 NIJE PRIKLJUČEN













U USB port priključen USB GPS U-blox7 receiver.
Windows 7 automatski počinje tražiti driver i nudi traženje sa Windows Update.
To je preskočeno.







Nakon što sam preskočio Windows Update, počinje instaliranje drivera i to traje oko minute do dvije.








U Device Manageru imamo:














3. INSTALIRANJE BktTimeSync v1.9.1

Pokrenuta datoteka BktTimeSync_Setup.exe









Na desktopu imamo prečac



Prvo pokretanje pita jezik sučelja





1. ISKLJUČITI Enable NTP (gornji desni kut)
2. U GPS Configuration za Serial Port postaviti postavke onakve kakve su za U-blox7 u Device Manager-u
3. Restart programa.
4. Nakon kratkog vremena program primi signal sa satelita i počinje sinkronizacija vremena.

BktTimeSync by IZ2BKT - Version 1.9.1

Internet Configuration

NTP server: Port: Offset: Enable NTP: ☐

Timeout: s

GPS Configuration

Serial Port: BAUD: Bit: Bit of Stop: Parity:

RTS: DTR: Max Error: s Offset: s

Always connected to the GPS: ☒ Protocol: Enable GPS: ☒

Coordinates: Altitude: WW Locator:

General Options

Start on windows startup: ☐ Start on system tray: ☐ Sync on startup: ☒

Sync every minutes (0 to manual sync) to second If error NTP try to use GPS: ☐

Maximum correction hours (0 = no limits) Checks updates every days (0 to disable)

Display notifications: ☐ Enable BktClock: ☐ Diagnostic Log: ☐

Synchronization Log: ☐


Local clock offset was -0.061000 seconds
 Last Sync :Thursday, December 20, 2018 17:34:44
 Time was successfully synchronized using GPS receiver
 Local clock offset was -0.002000 seconds
 Last Sync :Thursday, December 20, 2018 17:35:20
 Time was successfully synchronized using GPS receiver
 Local clock offset was 0.013000 seconds

Change Language [Web Site](#) [Forum](#)

Reduce in System Tray

Prikazivanje sata na desktopu – kvačica na **Enable BktClock**

Prikazuje poruku (samo jednom)



Konfiguriranje sata – dvoklik lijevom tipkom miša na bilo koju znamenku.

